

NEW TRASDATA (JTAG/BDM/BOOT) ECU APPLICATION LIST

Release F/16 (30/11/2016) referred to SW: 3.0.163.0 DLL: 1.0.175.0 FW: 8.007 build 0002

DIMSPORT Srl Località San Torio 88, Zona Industriale Madonnina 15020 Serralunga di Crea (AL) ITALY T +3901429552 F +390142940094

<http://www.dimSPORT.it> sales dept: info.race@dimSPORT.it; tech dept: support.race@dimSPORT.it

This application list is merely indicative. DimSPORT Srl reserves the right to modify the list without any notice and at any time.

La presente lista ha carattere meramente indicativo. DimSPORT Srl si riserva il diritto di apportare modifiche in qualunque momento e senza preavviso.

IMPORTANT WARNING

From TOS (Trasdata Operative System) firmware version 8.0, Internet connection required for reading and writing operations with NewTrasdata Master&Slave, mandatory.

The connections and the full functionality of the system will be guaranteed to all tools, regardless of subscription expiry date and plug-in families enabled.

A partire dalla versione firmware 8.0 del TOS (Trasdata Operative System), gli strumenti NewTrasdata Master&Slave richiedono la connessione Internet obbligatoria per operazioni di lettura e scrittura.

Lo stato degli abbonamenti o delle abilitazioni non influisce sulla connessione Internet: il funzionamento del sistema (sia software sia hardware) non cambierà in nessuna delle sue specifiche.

CPU SUPPORTED (GROUPS AND FAMILIES) / CPU SUPPORTATE (GRUPPI E SOTTOFAMIGLIE)

New/ Upg	GROUP ID	CPU GROUP / GRUPPO CPU	CPU FAMILIES INCLUDED IN THE GROUP / FAMIGLIE CPU INCLUSE NEL GRUPPO
	TF001	MOTOROLA MPC55X/MPC56X CPU group	-> 01 - MOTOROLA MPC55X/MPC56X (TM001)
	TF002	STMICROELECTRONICS ST10 CPU group	-> 02 - STMICROELECTRONICS ST10 (TM002) -> 05 - SPECIAL ST10 (TM005)
	TF003	INFINEON TRICORE CPU group	-> 03 - INFINEON TRICORE NO PSW (TM003) -> 04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004) -> 11 - INFINEON TRICORE SIEMENS SD16 PORSCHE (TM011) -> 12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012) -> 13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013) -> 14 - INFINEON TRICORE NO PSW KLINE (TM014) -> 15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015) -> 16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016) -> 18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018) -> 19 - INFINEON TRICORE BOSCH MEDC17 TPROT11 KIA/HYUNDAI (TM019) -> 20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD (TM020) -> 22 - INFINEON TRICORE BOSCH MEDC17 GPT BMW (TM022) -> 23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG (TM023) -> 24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO (TM024) -> 25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR/LAND ROVER (TM025) -> 26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL (TM026) -> 27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES (TM027) -> 28 - INFINEON TRICORE BOSCH MEDC17 GPT FORD (TM028) -> 29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA (TM029) -> 30 - INFINEON TRICORE BOSCH MEDC17 GPT MCLAREN (TM030) -> 31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT (TM031) -> 32 - INFINEON TRICORE BOSCH MEDC17 GPT NISSAN (TM032) -> 33 - INFINEON TRICORE BOSCH MEDC17 GPT ASTON MARTIN (TM033) -> 34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA (TM034) -> 35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA (TM035) -> 38 - INFINEON TRICORE BOSCH MED17 GPT DUCATI (TM038) -> 39 - INFINEON TRICORE BOSCH MEDC17 GPT TOYOTA (TM039) -> 40 - INFINEON TRICORE BOSCH MEDC17 GPT MAN (TM040) -> 41 - INFINEON TRICORE BOSCH MEDC17 GPT HYUNDAI/KIA (TM041) -> 42 - INFINEON TRICORE BOSCH MEDC17 GPT SUZUKI (TM042)
	TF004	MOTOROLA MPC55xx CPU group	-> 06 - NEXUS MOTOROLA MPC55xx (TM006)
	TF005	RENESAS SH7050 CPU group	-> 07 - RENESAS SH7050 (TM007)
	TF006	mitsubishi MH7xxx/MH8xxxx CPU group	-> 08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)
	TF007	MOTOROLA MC68xxx CPU group	-> 09 - MOTOROLA MC68xxx (TM009)
	TF008	MOTOROLA HC12 CPU group	-> 10 - MOTOROLA HC12 (TM010)
	TF009	RENESAS M32R CPU group	-> 17 - RENESAS M32R (TM017)
	TF010	NEC 76F00xx NBD CPU group	-> 36 - NEC 76F00xx NBD (TM036) NEC76F0038GD NEC76F0038AGD NEC76F0039GD NEC76F0039AGD NEC76F0040GD NEC76F0040AGD NEC76F0070 NEC76F0085
	TF011	FREESCALE ST MPC56xx SPC56x CPU group	-> 37 - MOTOROLA MPC56xx SPC56x (TM037)

ECU SUPPORTED / CENTRALINE SUPPORTATE

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
New/Upg	383	Agrale Cargo Truck	Bosch	EDC17C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52
	545	Agrale Cargo Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	94	Aprilia / Piaggio	IAW Marelli	5DM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E101
New	239	Aprilia / Piaggio	IAW Marelli	Z5M	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E101
New	909	Arctic Cat	Continental Siemens VDO	M3C	MC9S12XE256	TF008	10 - MOTOROLA HC12 (TM010)	
	898	Arctic Cat	Denso	32920-49x10	SH7054	TF005	07 - RENESAS SH705x (TM007)	
	727	Aston Martin	Bosch	ME17.8.31	TC1797	TF003	33 - INFINEON TRICORE BOSCH MEDC17 GPT ASTON MARTIN (TM033)	E94
	424	Aston Martin	FoMoCo	PCM150x	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E117
	721	Avia Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	NO CHECKSUM
	613	Bentley	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E84
	649	Bmc Cummins Engines	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	3	Bmw	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52
	100	Bmw	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	65	Bmw / Mini	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	485	Bmw / Yanmar	Bosch	EDC16C1-4.41	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52
	220	Bmw	Bosch	EDC17C41	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)	Hidden Mod Patch
	666	Bmw	Bosch	EDC17C41 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	Hidden Mod Patch
	221	Bmw	Bosch	EDC17C45	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)	Hidden Mod Patch
	670	Bmw	Bosch	EDC17C56	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	Hidden Mod Patch
	154	Bmw	Bosch	EDC17CP02	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	156	Bmw	Bosch	EDC17CP09 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	667	Bmw	Bosch	EDC17CP45 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	Hidden Mod Patch
	671	Bmw	Bosch	EDC17CP49	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	Hidden Mod Patch
	668	Bmw	Bosch	EDC17CP50/EDC17CP56 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	Hidden Mod Patch
New	903	BMW	Bosch	EDC17C76	TC1793	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	Hidden Mod Patch
	604	Bmw	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E19
	19	Bmw	Bosch	ME9	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E75
	229	Bmw	Bosch	ME9 2xDE28F800F3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E75
	103	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E75
	163	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E75
	148	Bmw / Mini / PSA Group	Bosch	MED17.2/MEV17.2 (ext. Flash)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	679	Bmw	Bosch	MEDV17.2.5/MEDV17.2.8/MEDV17.2.9	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	E94
	171	Bmw	Bosch	MEV1746	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	215	Bmw	Bosch	MEVD17.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	516	Bmw / Mini / PSA Group	Bosch	MEVD17.2.7	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	879	Bmw	Bosch	MEVD17.2.9	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	E94
	678	Bmw	Bosch	MEVD17.2.G/MEDV17.2.6	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)	E94
	18	Bmw	Siemens	MS45.0	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E77
	117	Bmw	Siemens	MSS 60 - MSS 65 #L	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E86
	116	Bmw	Siemens	MSS 60 - MSS 65 #R	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E86
	110	Bmw	Siemens	MSSV70 / MSS70	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E78
	136	Bmw Motorrad	Bosch	ME9 BMSK	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E95
	188	Bmw Motorrad	Bosch	ME9+ BMSK	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E75/E95
	452	Bmw Motorrad	Bosch	ME17.2 BMSX	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	890	Brilliance	Continental	STM2K-91 5WY54xxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E111
	552	Brp	Continental Siemens VDO	M3C S12XET256MAL	MC9S12XE256	TF008	10 - MOTOROLA HC12 (TM010)	E115
	536	Bugatti	Bosch	ME9.1.1	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E141
	124	Case (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	467	Case / New Holland	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94/E145
New	914	Caterham	EFI	CT1	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	
	392	Caterham	MBE	958	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	NO CHECKSUM
	704	Caterpillar	CAT	A5M8	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	
	440	Caterpillar	Caterpillar	Adem III (AT25160 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	NO CHECKSUM
	385	Caterpillar	Caterpillar	Adem III (AT25640 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	NO CHECKSUM
	648	Caterpillar	Caterpillar	Adem III (HWIII)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	NO CHECKSUM
	332	Caterpillar	Caterpillar	Adem IV (561/562)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	360	Caterpillar	Caterpillar	Adem IV (563/564 S29CD016G)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	408	Caterpillar	Caterpillar	Adem IV (563/564 S29CD032J)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	161	Caterpillar	Delphi	Perkins	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	323	CF Motor	Bosch	MSE3	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E122
	409	Chery	Bosch	ME7.9.7	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E118
	429	Chery	IAW Marelli	IAW4AC	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E101
	576	Chery	Siemens	STMK31	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E48
	17	Chevrolet / GM Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52
	74	Chevrolet / GM Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	660	Chevrolet / GM Group	Bosch	EDC16C39	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	519	Chevrolet / GM Group	Bosch	EDC16C42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	308	Chevrolet / GM Group	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E105
	202	Chevrolet / GM Group	Continental	STM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E111
	224	Chevrolet / GM Group / FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E114
	465	Chevrolet / GM Group / Opel	Delco	E83	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	E135
	14	Chrysler / Jeep	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52
	106	Chrysler / Jeep	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67
	503	Chrysler / Jeep	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	E94
	371	Chrysler / Jeep	Motorola	NCG4	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	E139
	372	Chrysler / Jeep	Motorola	NCG5	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	E139
	193	Cummins engines (generic)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	406	Cummins engines (Tractor generic)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	546	Cummins engines (Truck generic)	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	NO CHECKSUM

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
565	Cummins engines (Truck generic)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
582	Dacia	Siemens Continental	EMS3130	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E83
819	Daewoo	Delphi	MT60	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
619	Daewoo	Siemens	D42	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
361	Daewoo / Opel GM Group	Siemens	M300 B10D	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
134	Daf Truck	Bosch	EDC7C-C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
506	Daf Truck	Continental	CM2150C	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
403	Daf Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
142	Daf Truck	Delphi	DCM1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E76
125	Daf Truck	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
509	Daf Truck (Paccar Engine)	Delphi	PCX2	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E138
742	Daimler Truck (Cummins Engine)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
639	Daimler Trucks	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
543	Detroit Diesel Trucks	Temic	ACM2	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
627	Detroit Diesel Trucks	Temic	ACM2 - AT25256	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
144	Deutz / Fendt (AGCO Group)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
227	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
572	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
436	Deutz / Fendt (AGCO Group)	Bosch	EDC17CV56	ST10C167	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
160	Deutz / Fendt (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
80	Dodge	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
816	Dodge / FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C79	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
95	Dodge	Motorola	CM848B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
641	Dodge	Motorola	NCG5	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E139
860	Dodge	Motorola	NCG5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E139
473	Dodge	Siemens	SIM90T	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E110
566	Dodge (Cummins Engine)	Motorola	CM848E/CM849B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
635	Doosan	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
785	Doosan	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
791	Doosan	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
718	Ducati	Continental	M3D	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E115
341	Ducati	Continental Siemens VDO	M3C S12X256V	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)		E115
540	Ducati	Continental Siemens VDO	M3C S12XET256MAL	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)		E115
756	Ducati	Bosch	ME17.9.21	TC1724	TF003	38 - INFINEON TRICORE BOSCH MED17 GPT DUCATI		E94
653	Ducati	Melco	MH8106F	HIM8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)		E121
87	Ducati / MV Augusta	IAW Marelli	5SM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
394	Duramax	Bosch	EDC17CP18	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
786	FAW Jiefang	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
1	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
70	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
141	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
503	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
655	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C69	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
733	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C69	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
363	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
816	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17C79	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
905	FCA (Fiat/Chrysler Automobiles)	Bosch	ME2.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E94
847	FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
24	FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.10	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
30	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E49
27	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.6.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E91
26	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.6.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E93
659	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.0	TC1724	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
642	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.0	TC1724	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
150	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.1	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
643	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.3	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
823	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.5	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
515	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4AF.P2	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
380	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
381	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4GF	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
44	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4SF / 4DF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
63	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	55F8 / 55F9	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
28	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	55FHWxxx	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
91	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	6KPB	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E74
247	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	7GF	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
645	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8DF.11	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
382	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8F3	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
245	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
243	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GMF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
734	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GMK	SPC564A80	TF011	37 - MOTOROLA MPC56xx SRC56x (TM037)		E101
413	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8TDF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
726	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	9GF	SPC564A70	TF011	37 - MOTOROLA MPC56xx SRC56x (TM037)		E101
85	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
101	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
349	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3 HW04W	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
8	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6JF	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
303	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 8DF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E101
888	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 9DF	MPC5644A	TF011	37 - MOTOROLA MPC56xx SRC56x (TM037)		E101
856	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	CFC319 (gearbox)	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E68
83	FCA (Fiat/Chrysler Automobiles)	Siemens	SID803A 5WS40320	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
38	FCA (Fiat/Chrysler Automobiles) / PSA Group	Visteon	DCU-102	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E92
366	Fendt (AGCO Group)	Agco	Gearbox	ST10F269	TF002	05 - SPECIAL ST10 (TM005)		NO CHECKSUM
811	Fendt (AGCO Group)	Agco	Gearbox C167	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		NO CHECKSUM

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
335	Ferrari	Bosch	MED9.6.1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E113
42	Ferrari / Maserati	Bosch	ME7.3.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E89
823	Ferrari / FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.5	TC1793	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
121	Ford	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
230	Ford	Bosch	EDC17C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
698	Ford	Bosch	EDC17C10	TC1797	TF003	28 - INFINEON TRICORE BOSCH MEDC17 GPT FORD		E94
197	Ford	Bosch	EDC17CP05	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
737	Ford	Bosch	EDC17CP05	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
301	Ford	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
863	Ford	Bosch	EDC17C70	TC1793	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD		E94
76	Ford	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E70
586	Ford	Bosch	MED17.2	TC1767	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD		E94
831	Ford	Bosch	MED17.2	TC1767	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
872	Ford	Bosch	MED17.2	TC1767	TF003	28 - INFINEON TRICORE BOSCH MEDC17 GPT FORD		E94
618	Ford	Bosch	MED17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
200	Ford	Bosch	MED17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
279	Ford	Bosch	MEDG9.8	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E117
233	Ford	Delphi	DCM	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E62
302	Ford	Delphi	DCM3.5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
343	Ford	FoMoCo	JDS0	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E117
464	Ford	IAW Marelli	4AFR	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
393	Ford	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
663	Ford	Siemens	EMS2205	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
145	Ford	Siemens	SID206 5WS40483	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
460	Ford	Siemens	SID901	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E47
577	Ford	Siemens	SID902	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
749	Ford	Siemens Continental	EMS2204/2207/2211	TC1738	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E83
511	Ford	Siemens Continental	SID807EVO	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	OBDII Unlock Patch	E83
178	Ford	Siemens/Continental	SID807	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
20	Ford / Jaguar	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E62
510	Ford / Land Rover	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	OBDII Unlock Patch	E137
803	Ford / Land Rover	FoMoCo Continental	SID209	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E137
11	Ford / Mazda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
60	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
66	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
32	Ford / PSA Group / Volvo	Siemens	SID803 5WS40xxx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
78	Ford / PSA Group / Volvo	Siemens	SID803A 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
238	Ford / Volvo	Bosch	MED17.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
82	Ford / Volvo	Siemens	SID206 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
31	Ford Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
787	Ford Truck	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
504	Ford Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
784	Ford FRD	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
461	Freightliner / Mercedes Truck	Temic	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
684	Geely	Delphi	MT80	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
614	Generic Car/LCV	Bosch	EDC17CV42	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94
595	Generic Tractor	Recon	CM554	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
615	Generic Truck	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E94/E145
632	Generic Truck (Cummins Engine)	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
7	GM Group / Opel	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
228	GM Group / Opel	Bosch	EDC17C18	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
153	GM Group / Opel	Bosch	EDC17C19	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
688	GM Group / Opel	Bosch	EDC17C59	TC1767	TF003	26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL		E94
717	GM Group / Opel	Bosch	EDC17CP47	TC1797	TF003	26 - INFINEON TRICORE BOSCH MEDC17 GPT OPEL		E94
192	GM Group / Opel	Bosch	ME7.6.4	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E105
225	GM Group / Opel	Bosch	ME9.6	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E105
466	GM Group / Opel	Delco	E37	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E135
520	GM Group / Opel	Delphi	SH72544R	SH72544R	TF005	07 - RENESAS SH705x (TM007)		E100
605	GM Group / Opel	Delphi	DCM 3.7AP	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
706	GM Group / Opel	Denso	94661024	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
253	GM Group / Opel	Denso	1.7 DTI	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
295	GM Group / Opel	Denso	1.7 DTI SH7059	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
10	GM Group / Opel	IAW Marelli	MJD 6JF	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
111	GM Group / Opel	IAW Marelli	MJD 6O2.A6	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
107	GM Group / Opel	IAW Marelli	MJD 6O2.M1 - MJD 6O3.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
176	GM Group / Opel	IAW Marelli	MJD 6O2.M1 - MJD 6O3.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
333	GM Group / Opel	Siemens	SIMTEC 76	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
309	GM Group / Opel / Chevrolet	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E105
465	GM Group / Opel / Chevrolet	Delco	E83	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E135
458	GM Group / Opel / Chevrolet	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
322	GM Group / Opel / Isuzu	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
348	GM Group / Opel / Suzuki	IAW Marelli	MJD 6O2.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E101
84	Great Wall Motor	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
470	Great Wall Motor	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
439	Great Wall Motor	Bosch	ME7.8.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E127
388	Great Wall Motor	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
487	Hino	Denso	895xx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
347	Hino	Denso	896xx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
833	Hino	Denso	175822-799	76F0039AGD	TF010	36 - NEC NBD		E151
12	Honda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
731	Honda	Bosch	EDC17C58	TC1793	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
805	Honda	Bosch	EDC17CP50	TC1797	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
172	Honda	Bosch	EDC17CP06	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
213	Honda	Bosch	EDC17CP16	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
497	Honda	Bosch	ME7.9.3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
810	Honda	Bosch	ME17.9.3	TC1793	TF003	35 - INFINEON TRICORE BOSCH MEDC17 GPT HONDA		E94
730	Honda	Keihin	37805-Pxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
492	Honda	Keihin	37805-Rxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
617	Honda	Keihin	37820-RAH	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
61	Hyundai / Kia	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
72	Hyundai / Kia	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
164	Hyundai / Kia	Bosch	EDC17C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
608	Hyundai / Kia	Bosch	EDC17C53	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
682	Hyundai / Kia	Bosch	EDC17C57	TC1793	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
127	Hyundai / Kia	Bosch	EDC17CP14	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
549	Hyundai / Kia	Bosch	EDC17CP14	TC1796	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
683	Hyundai / Kia	Bosch	M7.9	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E14
167	Hyundai / Kia	Bosch	M7.9.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E106
339	Hyundai / Kia	Bosch	ME17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
597	Hyundai / Kia	Bosch	ME7.9.7	ST10F275	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
496	Hyundai / Kia	Bosch	MED17.9.8	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
550	Hyundai / Kia	Bosch	MED17.9.8/MEDG17.9.8	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
416	Hyundai / Kia	Bosch	MEG17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
693	Hyundai / Kia	Bosch	MEG17.9.2	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
867	Hyundai / Kia	Bosch	EDC17C53	TC1767	TF003	41 - INFINEON TRICORE BOSCH MEDC17 GPT HYUNDAI/KIA		E94
858	Hyundai / Kia	Bosch	EDC17CP62	TC1793	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA		E94
194	Hyundai / Kia	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E111
387	Hyundai / Kia	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)		E100
317	Hyundai / Kia	Keftco	EH8	MH8305H	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
351	Hyundai / Kia	Keftco	KTS3	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
575	Hyundai / Kia	Mitsubishi	S9106-3945x	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
367	Hyundai / Kia	Siemens	SIM2K-47 5WY4Cxxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
368	Hyundai / Kia	Siemens	SIM2K-47 5WY4Cxxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
352	Hyundai / Kia	Siemens	SIMK43 5WY1xxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
353	Hyundai / Kia	Siemens	SIMK43 5WY44xxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
354	Hyundai / Kia	Siemens	SIMK43 5WY44xxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
521	Hyundai / Kia	Siemens Continental	SIM2K	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E111
169	Hyundai / Kia (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
112	Hyundai / Kia / Ssangyong	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E81
881	Hyundai Seasall	Delphi	ETC3	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E138
623	Hyundai Trago	Delphi	ETC3	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E138
621	International Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
874	International Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
804	International Truck	Siemens	SID904	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
400	International Truck (Cummins)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
401	International Truck (Cummins)	Motorola	CM871 / CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
745	Isuzu	Bosch	EDC17CV41	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
412	Isuzu	Denso	25841077	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
852	Isuzu	Denso	275800-8755	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
430	Isuzu	Transtron	4jxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
490	Isuzu	Transtron	Transtron	SH72544R	TF005	07 - RENESAS SH705x (TM007)		E121
703	Isuzu	Transtron	Transtron SH7059	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
313	Isuzu	Transtron	Transtron	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
79	Isuzu / Chevrolet	Delphi		MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E82
322	Isuzu / GM Group / Opel	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
579	Isuzu Giga	Denso	895xx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
130	Iveco	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
140	Iveco	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
206	Iveco	Bosch	EDC17	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
432	Iveco	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
633	Iveco	Bosch	EDC17CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E145
568	Iveco	IAW Marelli	5Sf4	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
129	Iveco / New Holland	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E63
137	Iveco / New Holland	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
346	Jaguar	Denso	MB079700	SH7055	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
422	Jaguar	Denso	MB279700-9xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
105	Jaguar	Siemens	SID201 - SID204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
845	Jaguar / Land Rover	Bosch	EDC17CP55	TC1793	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
864	Jaguar / Land Rover	Bosch	EDC17CP55	TC1793	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD		E94
685	Jaguar / Land Rover	Bosch	MED17.8.31	TC1797	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
828	Jaguar / Land Rover	Bosch	MED17.9	TC1793	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
827	Jaguar / Land Rover	Bosch	MED17.9.7	TC1767	TF003	25 - INFINEON TRICORE BOSCH MEDC17 GPT JAGUAR (TM025)		E94
498	Jaguar / Land Rover	Denso	PS.05C	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
593	JCB	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
560	JCB	Delphi	DCM TIER III	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
701	JCB	Delphi	DCM3.3	SH72544R	TF005	07 - RENESAS SH705x (TM007)		E100
402	JCB / Massey Ferguson	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
191	JCB Fastrack	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
807	JMC	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
598	Jeep	Bosch	EDC17C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
256	Jeep	Bosch	EDC17CP27	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
77	Jeep / Mitsubishi	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
190	John Deere	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
462	John Deere	Phoenix	L11	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
123	John Deere	Phoenix	L14	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E104
236	John Deere	Phoenix	L16	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
463	John Deere	Phoenix	L4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
508	John Deere	Phoenix	L9/L11	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E104
457	John Deere	Siemens	UIC2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
876	Kawasaki	Denso	21175-0028	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
818	Kawasaki	Denso	21175-0077	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
877	Kawasaki	Denso	21175-0109/0111/0113/114	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
817	Kawasaki	Denso	21175-0187	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
882	Kawasaki	Denso	21175-0199	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
525	Kawasaki	Denso	21175-0220	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
854	Kawasaki	Denso	21175-027X/03XX		TF009	17 - RENESAS M32R (TM017)		E121
687	Kawasaki	Denso	21175-03XX	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
652	Kawasaki	Denso	21175-08XX	M32R196	TF009	17 - RENESAS M32R (TM017)		E121
522	Kawasaki	Denso	21775-0046	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
532	Kawasaki	Denso	21775-0097	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
620	Kawasaki	Denso	21775-07XX	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
561	Kawasaki	Denso	21775-109X	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
530	Kawasaki	Melco	21175-3732	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
455	Kawasaki	Melco	MH8106F	ULTRA 300x	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
637	Kawasaki	Mitsubishi	21175-033X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
625	Kawasaki	Mitsubishi	21175-076X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
285	Kawasaki	Mitsubishi	JetSki Ultra 250	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
300	Kawasaki	Mitsubishi	ZRX1200	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
484	Kawasaki	Mitsubishi	ZX10R	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
488	Kawasaki	Mitsubishi	ZX10R MY07	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx		E121
744	Kenworth Truck (Cummins Engine)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
541	Khodro/Saipa	Continental	SI2M2K-34 5WY5Kxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E48
379	King Long	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
438	Komatsu	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
418	Ktm	Bosch	M17.8.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
773	Kubota	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
584	Kubota	Denso	275700-1201	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
578	Kubota	Denso	275800-7221	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
911	Kymco	Continental Siemens VDO	M3C	MC9512XE256	TF008	10 - MOTOROLA HC12 (TM010)		
376	Lada / UAZ	Bosch	M7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
428	Lada / UAZ	Bosch	ME17.9.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
469	Lamborghini	Campi	Campi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
869	Lamborghini	Campi	LIE	MPC5567	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		
904	Lamborghini	IAW Marelli	CFC311	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		
120	Land Rover	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
177	Land Rover	Bosch	EDC17CP11	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
235	Land Rover	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
483	Land Rover	Denso	MB279700-94xx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
98	Land Rover	Siemens	SID201 - SID204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
115	Land Rover	Siemens	SID203 5WS40371	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
384	Land Rover	Siemens	SID204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E68
37	Land Rover	Visteon	DCU-106	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E92
510	Land Rover / Ford	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)		E137
498	Land Rover / Jaguar	Denso	P5.05C	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
310	LDV	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
567	Lindner Perkins	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
287	Lotus	Efi	Efi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
306	Lotus	Efi	Efi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		NO CHECKSUM
437	Lotus	Efi	T4E	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E129
507	Lotus	Efi	T6E	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E129
447	LTI	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
453	Mack	Bosch	EDC7U/U1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E130
21	Mahindra	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
699	Mahindra	Bosch	EDC16 C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
558	Mahindra	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
495	Mahindra	Bosch	EDC17C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
900	Mahindra	Bosch	EDC17C63	TC1724	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
538	Man Latin America / Volkswagen Trucks	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		NO CHECKSUM
135	Man Truck	Bosch	EDC7C3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E66
139	Man Truck	Bosch	EDC7C32	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
832	Man Truck	Bosch	EDC17CV42	TC1797	TF003	40 - INFINEON TRICORE BOSCH MEDC17 GPT MAN (TM040)		E94
596	Maserati	Bosch	EDC17C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)		E94
226	Maserati	Bosch	ME911	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E113
711	Maserati	Bosch	MED17.3.4	TC1797	TF003	29 - INFINEON TRICORE BOSCH MEDC17 GPT FCA		E94
402	Massey Ferguson / JCB	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
270	Massey Ferguson / McCormick / Caterpillar	Perkins	Caterpillar Tier2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
826	Maxforce	Motorola	ECM0563	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		
651	Maz Trucks	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
395	Mazda	Denso	N3J1	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
263	Mazda	Denso	R2AX	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
278	Mazda	Denso	RF7K	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
476	Mazda	Denso	L3T4	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
518	Mazda	Denso	L3TA	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
321	Mazda	Denso	L831	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
327	Mazda	Denso	R2AA	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
277	Mazda	Denso	RF8G	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
344	Mazda	Denso	ZJ77	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
454	Mazda	Denso	ZY9E	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
517	Mazda	Mitsubishi	E6T540xxxx	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
603	Mazda	Mitsubishi	E6T58xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
373	Mazda	Mitsubishi	E6T5x	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
475	Mazda	Mitsubishi	FPV1EA	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
345	Mazda	Mitsubishi	L3B1	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
708	McLaren	Bosch	MED17.8.3	TC1797	TF003	30 - INFINEON TRICORE BOSCH MEDC17 GPT MCLAREN		E94
4	Mercedes	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
71	Mercedes	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
97	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
114	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
222	Mercedes	Bosch	EDC17C01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
231	Mercedes	Bosch	EDC17C43	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
700	Mercedes	Bosch	EDC17C57	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
710	Mercedes	Bosch	EDC17C66	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
157	Mercedes	Bosch	EDC17CP01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
155	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
182	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
273	Mercedes	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
365	Mercedes	Bosch	EDC17CP46	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
691	Mercedes	Bosch	EDC17CP46	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
622	Mercedes	Bosch	ME2.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E106
102	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E79
204	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E79
692	Mercedes	Bosch	MED17.7.2	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
736	Mercedes	Bosch	MED17.7.1/MED17.7.3	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
740	Mercedes	Bosch	MED17.7.3.1	TC1797	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
249	Mercedes	Bosch	MED17.1	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
714	Mercedes	Bosch	MED17.7.5	TC1793	TF003	27 - INFINEON TRICORE BOSCH MEDC17 GPT MERCEDES		E94
514	Mercedes	Bosch	MED17.7.8	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
248	Mercedes	Delphi	CRD2.10	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)		E100
808	Mercedes	Delphi	CRD3.40	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
809	Mercedes	Delphi	CRD3.50	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E83
119	Mercedes	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E81
580	Mercedes	Siemens	EGS52	ST10C167	TF002	05 - SPECIAL ST10 (TM005)		E146
581	Mercedes	Siemens	EGS53	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E146
175	Mercedes	Siemens	SIM 266	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E124
500	Mercedes	Siemens	SIM 266 (ex flash S29CD032J)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E124
542	Mercedes Truck	Continental	HDEP	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
628	Mercedes Truck	Continental	HDEP MCM2.1	TC1797	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
461	Mercedes Truck / Freightliner	Temic	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)		E132
189	Mercury Marine	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
33	Mercury Marine	Motorola	ECM04xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
442	Mercury Marine	Motorola	ECM0501	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
90	Mercury Marine	Motorola	ECM070xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
132	Mercury Marine	Motorola	ECM555	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
36	Mercury Marine	Motorola	PCM308	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
35	Mercury Marine	Motorola	PCM702	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
441	Mercury Marine	Motorola	PCM08xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
34	Mercury Marine	Motorola	PCMBE0101	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E119
419	MG	Bosch	ME7.9.71	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E118
891	MG	Bosch	ME17.8.8	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
152	Mini	Bosch	MED172/MEV172 (irom)	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
237	Mini	Bosch	MEV17.2.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
208	Mini	Bosch	MEVD17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
719	Mini	Bosch	MEVD17.2.3	TC1793	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW (TM022)		E94
43	Mitsubishi	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
640	Mitsubishi	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
170	Mitsubishi	Bosch	EDC17CP15 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
588	Mitsubishi	Bosch	EDC17CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
573	Mitsubishi	Bosch	ME7.7.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E144
265	Mitsubishi	Denso	(4D56 engine)	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
601	Mitsubishi	Denso	6M60	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
629	Mitsubishi	Denso	6M60	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
283	Mitsubishi	Denso	EVOX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
319	Mitsubishi	Denso	RA6	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
417	Mitsubishi	Denso	RA6 4D56	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
324	Mitsubishi	Denso	RA6 4N13	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
232	Mitsubishi	IAW Marelli	4AM	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
337	Mitsubishi	IAW Marelli	4CM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
444	Mitsubishi	IAW Marelli	4DM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
423	Mitsubishi	IAW Marelli	4GM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
589	Mitsubishi	IAW Marelli	4GT	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
548	Mitsubishi	IAW Marelli	IAW4DM CR47	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
350	Mitsubishi	Melco	G1Tx	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
318	Mitsubishi	Mitsubishi	3.2 D	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
894	Mitsubishi	Mitsubishi	21175-1118	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
570	Mitsubishi	Mitsubishi	E2T1xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
609	Mitsubishi	Mitsubishi	E2T79xxx	MH8306F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
449	Mitsubishi	Mitsubishi	E2T7xxx MH7203	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
479	Mitsubishi	Mitsubishi	E6T310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
493	Mitsubishi	Mitsubishi	E6T310xxx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
585	Mitsubishi	Mitsubishi	E6T36xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
474	Mitsubishi	Mitsubishi	E6T38xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
482	Mitsubishi	Mitsubishi	E6T41xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
602	Mitsubishi	Mitsubishi	E6T44xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
410	Mitsubishi	Mitsubishi	E6T47xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
391	Mitsubishi	Mitsubishi	E6T49xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
583	Mitsubishi	Mitsubishi	E6T74xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
426	Mitsubishi	Mitsubishi	E6T76xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
328	Mitsubishi	Mitsubishi	E6T7xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
893	Mitsubishi	Mitsubishi	E6T97xx	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
329	Mitsubishi (Colt 1.5 asp.)	Mitsubishi	MH7x/MH8x	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
255	Mitsubishi (Colt 1.5 turbo)	Mitsubishi	MH7x/MH8x	MH8203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
261	Mitsubishi (Lancer EVO IX)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
259	Mitsubishi (Lancer EVO VI)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
260	Mitsubishi (Lancer EVO VII/VIII)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		NO CHECKSUM
297	Mitsubishi (Pajero 3.2 DI-D)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		E121
99	Mitsubishi / Smart	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
547	Moto Guzzi	IAW Marelli	IAW7SM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
217	MV Agusta	IAW Marelli	7BM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		NO CHECKSUM
143	New Holland	Bosch	EDC16+ C39/UC40	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
467	New Holland / Case	Bosch	EDC17C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94/E145
129	New Holland / Iveco	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E63
137	New Holland / Iveco	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
478	Nissan	Bosch	EDC16CP42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
657	Nissan	Bosch	EDC17C45	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
724	Nissan	Bosch	EDC17C84	TC1782	TF003	32 - INFINEON TRICORE BOSCH MEDC17 GPT NISSAN		E94
294	Nissan	Denso	1H	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
264	Nissan	Denso	D3	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
314	Nissan	Denso	HP	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
315	Nissan	Denso	HWII	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
647	Nissan	Hitachi	23710-5Y222	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
445	Nissan	Hitachi	A56-B7x	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
450	Nissan	Hitachi	A56-C1x	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
661	Nissan	Hitachi	A56-U45	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
481	Nissan	Hitachi	BED301-000	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
448	Nissan	Hitachi	DEA030-2xx	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
296	Nissan	Hitachi	HPNGV	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
396	Nissan	Hitachi	HPNGV SH7059	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
298	Nissan	Hitachi	HW 1	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
299	Nissan	Hitachi	HW 4	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
502	Nissan	Hitachi	MEC-100-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
414	Nissan	Hitachi	MEC-107	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
494	Nissan	Hitachi	MEC-23-xxx	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
451	Nissan	Hitachi	MEC-30-07x	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
600	Nissan	Hitachi	MEC-35	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
650	Nissan	Hitachi	MEC-37-3xx	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
680	Nissan	Hitachi	MEC-37-900	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
694	Nissan	Hitachi	MEC-38-310	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
415	Nissan	Hitachi	MEC-73-xxx	SH7059	TF005	07 - RENESAS SH705x (TM007)		E121
606	Nissan	Hitachi	MEC-78-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
501	Nissan	Hitachi	MEC-90-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
587	Nissan	Hitachi	MEC-940-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
486	Nissan Truck (Cummins engine)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
431	Peterbilt Truck (Cummins engine)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
377	Piaggio	Bosch	EDC17C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
307	Polaris	Bosch	M17.8.7	TC1762	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
673	Polaris	Bosch	M17.9.74	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
56	Polaris	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
57	Polaris	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
282	Polaris	Bosch	ME7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E71
240	Porsche	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
242	Porsche	Bosch	ME7.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
41	Porsche	Bosch	ME7.8.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E27
40	Porsche	Bosch	ME7.8.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E87
159	Porsche	Bosch	ME7.8.2 min	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E87
793	Porsche	Bosch	MED17.1.11	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
39	Porsche	Siemens/Continental	VDO SDI3/SDI4	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)		E96
272	Porsche	Siemens/Continental	VDO SDI6	TC1796	TF003	11 - INFINEON TRICORE SIEMENS SDI6 PORSCHE (TM011)		E96
108	Porsche / VAG (VW Group)	Bosch	MED9.1 FSI - MED9.1.1 FSI	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E58/E85/E123
534	Proton	Siemens VDO	PW5XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E140
5	Proton	Siemens VDO	PW8XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E140
118	PSA Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
118	PSA Group	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
728	PSA Group	Bosch	EDC17C60	TC1793	TF003	34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
198	PSA Group	Bosch	EDC17CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
219	PSA Group	Bosch	EDC17C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
312	PSA Group	Bosch	EDC17CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
551	PSA Group	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
397	PSA Group	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
25	PSA Group	Bosch	ME7.4.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
569	PSA Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E32
47	PSA Group	Bosch	ME7.4.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
824	PSA Group	Bosch	ME7.4.9 NG	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E88
729	PSA Group	Bosch	MED17.4.4	TC1793	TF003	34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA		E94
196	PSA Group	Bosch	MED17.4/MEV17.4	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
305	PSA Group	Bosch	MED17.4/MEV17.4 (Irom)	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94

New / Upg	PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) /		PATCH UNLOCK /	CHECKSUM MOD. /
							FAMIGLIA CPU (SPEC.)			
	209	PSA Group	Bosch	MED17.4/MEV17.4 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	286	PSA Group	Bosch	MEV17.4.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	216	PSA Group	Bosch	MEV017.4.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	741	PSA Group	Bosch	MEV017.4.4	TC1793	TF003	34 - INFINEON TRICORE BOSCH MEDC17 GPT PSA	E94		
	257	PSA Group	Delphi	DCM3.4	SH7058	TF005	07 - RENESAS SH705x (TM007)	E100		
	362	PSA Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH705x (TM007)	E100		
	244	PSA Group	Delphi	DCM3.5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	E100		
	55	PSA Group	Delphi	DDCR	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E100		
	45	PSA Group	IAW Marelli	6LP1.49	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E74		
	46	PSA Group	IAW Marelli	6LPC.102	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E74		
	599	PSA Group	Siemens	S2000	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E60		
	104	PSA Group	Siemens	SID201 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E68		
	443	PSA Group	Siemens	SID801	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E26		
	320	PSA Group	Siemens/Continental	SID807 (irom)	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	E83		
	359	PSA Group	Siemens/Continental	SID807 (xrom)	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)	E83		
	122	PSA Group	Valeo Johnson	J34P	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E103		
	211	PSA Group	Valeo Johnson	J34P	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E103		
	491	PSA Group	Valeo Johnson	J34P HW II	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E103		
	6	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52		
	133	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52		
	29	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67		
	62	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67		
	69	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67		
	223	Renault Group	Bosch	EDC16C36	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67		
	234	Renault Group	Bosch	EDC16CP33	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67		
	201	Renault Group	Bosch	EDC17C11	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	181	Renault Group	Bosch	EDC17CP19	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	456	Renault Group	Bosch	EDC17CP58	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	790	Renault Group	Bosch	EDC17C84	TC1782	TF003	31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT	E94		
	720	Renault Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E32		
	709	Renault Group	Bosch	MED17.9.20	TC1782	TF003	31 - INFINEON TRICORE BOSCH MEDC17 GPT RENAULT	E94		
	258	Renault Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH705x (TM007)	E100		
	529	Renault Group	Hitachi	A56-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	799	Renault Group	Hitachi	EV20-0xx	SH7055	TF005	07 - RENESAS SH705x (TM007)	E121		
	531	Renault Group	Hitachi	MEC121-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	571	Renault Group	Hitachi	MEC800	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	768	Renault Group	Hitachi	MEC099-xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	88	Renault Group	Sagem	S2000RPM	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E60		
	250	Renault Group	Sagem	S3000	SH7055	TF005	07 - RENESAS SH705x (TM007)	E73		
	210	Renault Group	Siemens	EMS3110	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)	E83		
	844	Renault Group	Siemens	EMS3134	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E28		
	81	Renault Group	Siemens	SID301	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E83		
	205	Renault Group	Siemens	SID305	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)	E83		
	252	Renault Group	Siemens	SIM32	SH7055	TF005	07 - RENESAS SH705x (TM007)	E73		
	336	Renault Group	Siemens	SIRIUS 32	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E25		
	471	Renault Group	Siemens	SIRIUS 34	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	E28		
	280	Renault Group	Valeo	S3000	SH7058	TF005	07 - RENESAS SH705x (TM007)	E73		
	251	Renault Group	Valeo	V40	SH7058	TF005	07 - RENESAS SH705x (TM007)	E73		
	398	Renault Group / Nissan	Bosch	EDC17C42	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	292	Renault Group / Samsung	Hitachi	DA A56-Y8x	SH7055	TF005	07 - RENESAS SH705x (TM007)	E121		
	138	Renault Truck / Volvo Truck	TRW	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E80		
	330	Rotax	Siemens VDO	MSE 3.7	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E126		
	411	Rotax	Siemens VDO	MSE 3.7 R/H3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E126		
	180	Rotax (Sea Doo Acqua Scooter)	Bosch	ME17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	878	Saab	Bosch	EDC17CP21	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	654	Same	Bosch	EDC17C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	590	Scania Truck	Continental	EMS S7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E64		
	594	Scania Truck	Continental	EMS S8	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	E64		
	131	Scania Truck	Motorola	EDCS6	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E64		
	738	Sinotruck	Bosch	EDC17CV44	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	23	Smart	Bosch	ME7.7.0	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E90		
	480	Smart	Mitsubishi	G2T601x Gearbox	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx	E121		
	459	Ssangyong	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH705x (TM007)	E100		
	524	Ssangyong	Delphi	DCM 3.7	SH72544R	TF005	07 - RENESAS SH705x (TM007)	E100		
	22	Ssangyong	Delphi	DCM 3.7	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E65		
	564	Subaru	Denso	112200-8481	SH7055	TF005	07 - RENESAS SH705x (TM007)	E121		
	630	Subaru	Denso	112300-0430	SH7055	TF005	07 - RENESAS SH705x (TM007)	E121		
	281	Subaru	Denso	CJ	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	375	Subaru	Denso	DM	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	276	Subaru	Denso	DT	SH7059	TF005	07 - RENESAS SH705x (TM007)	E121		
	275	Subaru	Denso	KS	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	644	Subaru	Hitachi	DEF002-XXX	SH7059	TF005	07 - RENESAS SH705x (TM007)	E121		
	16	Suzuki	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52		
	212	Suzuki	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52		
	446	Suzuki	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E67		
	883	Suzuki	Bosch	EDC17C49	TC1797	TF003	42 - INFINEON TRICORE BOSCH MEDC17 GPT SUZUKI (TM042)	E94		
	340	Suzuki	Bosch	ME17.8.XX	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	434	Suzuki	Bosch	ME17.8.XX	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94		
	880	Suzuki	Bosch	MED17.9.63	TC1793	TF003	42 - INFINEON TRICORE BOSCH MEDC17 GPT SUZUKI (TM042)	E94		
	370	Suzuki	Denso	057L1	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		
	331	Suzuki	Denso	076x	SH7055	TF005	07 - RENESAS SH705x (TM007)	E121		
	262	Suzuki	Denso	1.3 MT	SH7055	TF005	07 - RENESAS SH705x (TM007)	E121		
	316	Suzuki	Denso	1.6 MT	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121		

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
New/Upg	533	Suzuki	Denso	32920-01H000	SH7054	TF005	07 - RENESAS SH705x (TM007)	E121
	853	Suzuki	Denso	32920-04KA0		TF009	17 - RENESAS M32R (TM017)	E121
	528	Suzuki	Denso	32920-08J11	M32R196	TF009	17 - RENESAS M32R (TM017)	E121
	523	Suzuki	Denso	32920-21Hxxx	M32R196	TF009	17 - RENESAS M32R (TM017)	E121
	672	Suzuki	Denso	32920-24FXX	SH7054	TF005	07 - RENESAS SH705x (TM007)	E121
	526	Suzuki	Denso	32920-30G00	SH7054	TF005	07 - RENESAS SH705x (TM007)	E121
	822	Suzuki	Denso	32920-31300	SH7058	TF005	07 - RENESAS SH705x (TM007)	E121
	557	Suzuki	Denso	3C3/2C0-8591A-XX	SH7054	TF005	07 - RENESAS SH705x (TM007)	E121
	364	Suzuki	IAW Marelli	8DS	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55xx (TM006)	E101
	9	Suzuki	IAW Marelli	U213DT	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E101
	616	Suzuki	Mitsubishi	33920-93J40	MH5xxxF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	NO CHECKSUM
New	896	Suzuki	Mitsubishi	33920-96L10	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
	865	Suzuki	Mitsubishi	33920-98JF0	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	E121
	489	Suzuki	Mitsubishi	E6T13xxx	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	NO CHECKSUM
	369	Suzuki	Mitsubishi	E6T172	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	E121
	355	Suzuki	Mitsubishi	E6T900 M0	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	E121
New	895	Suzuki	Mitsubishi	E6T91571H	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	E121
New	897	Suzuki	Mitsubishi	E6T91695H	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	E121
	348	Suzuki / GM Group / Opel	IAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E101
	254	Suzuki Outboard	Melco		MH7203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	NO CHECKSUM
	477	Suzuki Outboard	Melco		MH7202	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	NO CHECKSUM
	15	Tata	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E65
	636	Tata	IAW Marelli	MJD 602	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E101
	404	Tata Trucks (Cummins)	Motorola	CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	722	Tigercat (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	NO CHECKSUM
	13	Toyota	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	E52
	775	Toyota	Bosch	EDC17C73	TC1793	TF003	39 - INFINEON TRICORE BOSCH MEDC17 GPT TOYOTA	E94
	195	Toyota	Bosch	EDC17CP07	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	E94
	356	Toyota	Bosch	ME7.9.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E97
	54	Toyota	Bosch	ME7.9.51	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	E97
	759	Toyota	Denso	175822-666	76F0040GD	TF010	36 - NEC NBD (TM036)	E151
	777	Toyota	Denso	175822-737	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	776	Toyota	Denso	175822-737	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	758	Toyota	Denso	175822-762	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	769	Toyota	Denso	175822-762	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	746	Toyota	Denso	175822-773	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	764	Toyota	Denso	175822-773	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	770	Toyota	Denso	175822-773	76F0039AGD	TF010	36 - NEC NBD (TM036)	E151
	783	Toyota	Denso	175822-773	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	755	Toyota	Denso	175822-887	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	875	Toyota	Denso	175822-887	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	782	Toyota	Denso	175822-887	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	795	Toyota	Denso	175822-887	76F0040AGD	TF010	36 - NEC NBD (TM036)	E151
	821	Toyota	Denso	175822-887	76F0040AGD	TF010	36 - NEC NBD (TM036)	E151
	774	Toyota	Denso	175822-887	76F0040GD	TF010	36 - NEC NBD (TM036)	E151
	765	Toyota	Denso	176522-762	76F0039AGD	TF010	36 - NEC NBD (TM036)	E151
	766	Toyota	Denso	176622-762	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	838	Toyota	Denso	21175-2540	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	763	Toyota	Denso	211941-37910830	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	861	Toyota	Denso	211941-45900930	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	884	Toyota	Denso	275036-0360	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	815	Toyota	Denso	275036-0360	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	753	Toyota	Denso	275036-1152	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	778	Toyota	Denso	275036-1152	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	840	Toyota	Denso	275036-1152	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	752	Toyota	Denso	275036-1152	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	814	Toyota	Denso	275036-1152	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	908	Toyota	Denso	275036-1152	76F0039AGD	TF010	36 - NEC NBD (TM036)	E151
	846	Toyota	Denso	275036-1470	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	760	Toyota	Denso	275036-2110	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	843	Toyota	Denso	275036-2440	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	796	Toyota	Denso	275036-3410	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	857	Toyota	Denso	275036-3410	76F0070	TF010	36 - NEC NBD (TM036)	E151
	761	Toyota	Denso	275036-3560	76F0070	TF010	36 - NEC NBD (TM036)	E151
	886	Toyota	Denso	275036-3740	76F0039AGD	TF010	36 - NEC NBD (TM036)	E151
	806	Toyota	Denso	275036-4520	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	747	Toyota	Denso	275036-4820	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	851	Toyota	Denso	275036-4820	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	779	Toyota	Denso	275036-5130	76F0070	TF010	36 - NEC NBD (TM036)	E151
	801	Toyota	Denso	275036-5280	76F0085	TF010	36 - NEC NBD (TM036)	E151
	839	Toyota	Denso	275036-5650	76F0085	TF010	36 - NEC NBD (TM036)	E151
	812	Toyota	Denso	275036-6941	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	798	Toyota	Denso	275036-7341	76F0040GD	TF010	36 - NEC NBD (TM036)	E151
	873	Toyota	Denso	275036-7461	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	772	Toyota	Denso	275036-7780	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	797	Toyota	Denso	275036-8730	76F0038GD	TF010	36 - NEC NBD (TM036)	E151
	781	Toyota	Denso	275036-9160	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	855	Toyota	Denso	275036-9160	76F0039GD	TF010	36 - NEC NBD (TM036)	E151
	754	Toyota	Denso	275036-9170	76F0038AGD	TF010	36 - NEC NBD (TM036)	E151
	820	Toyota	Denso	275036-9170	76F0040GD	TF010	36 - NEC NBD (TM036)	E151
	767	Toyota	Denso	275922-001	76F0070	TF010	36 - NEC NBD (TM036)	E151
	762	Toyota	Denso	275922-022	76F0085	TF010	36 - NEC NBD (TM036)	E151
	836	Toyota	Denso	275922-092	76F0070	TF010	36 - NEC NBD (TM036)	E151

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
771	Toyota	Denso	275922-473	76F0085	TF010	36 - NEC NBD (TM036)		E151
802	Toyota	Denso	275922-500	76F0085	TF010	36 - NEC NBD (TM036)		E151
841	Toyota	Denso	275922-532	76F0085	TF010	36 - NEC NBD (TM036)		E151
837	Toyota	Denso	275922-5920	76F0070	TF010	36 - NEC NBD (TM036)		E151
794	Toyota	Denso	275992-428	76F0070	TF010	36 - NEC NBD (TM036)		E151
2	VAG (VW Group)	Bosch	EDC16 U2.1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	OBDDII Unlock Patch	E52
96	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	OBDDII Unlock Patch	E67
109	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	OBDDII Unlock Patch	E67
67	VAG (VW Group)	Bosch	EDC16+ U34	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)	OBDDII Unlock Patch	E67
149	VAG (VW Group)	Bosch	EDC17 U01	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
207	VAG (VW Group)	Bosch	EDC17 U05 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
199	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	OBDDII Unlock Patch	E94
269	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	OBDDII Unlock Patch	E94
420	VAG (VW Group)	Bosch	EDC17C54	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
675	VAG (VW Group)	Bosch	EDC17C64	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
705	VAG (VW Group)	Bosch	EDC17C74	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
126	VAG (VW Group)	Bosch	EDC17CP04	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
425	VAG (VW Group)	Bosch	EDC17CP14	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	OBDDII Unlock Patch	E94
716	VAG (VW Group)	Bosch	EDC17CP14	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG	OBDDII Unlock Patch	E94
146	VAG (VW Group)	Bosch	EDC17CP14 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	OBDDII Unlock Patch	E94
151	VAG (VW Group)	Bosch	EDC17CP14 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	OBDDII Unlock Patch	E94
665	VAG (VW Group)	Bosch	EDC17CP14 TPROT7.0 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
166	VAG (VW Group)	Bosch	EDC17CP14 USA ext. flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	OBDDII Unlock Patch	E94
427	VAG (VW Group)	Bosch	EDC17CP20 (rom)	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
165	VAG (VW Group)	Bosch	EDC17CP20 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
187	VAG (VW Group)	Bosch	EDC17CP20 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
902	VAG (VW Group)	Bosch	EDC17CP20 internal rom	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
162	VAG (VW Group)	Bosch	EDC17CP24 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
203	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
268	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
676	VAG (VW Group)	Bosch	EDC17CP44	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
901	VAG (VW Group)	Bosch	EDC17C46	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
739	VAG (VW Group)	Bosch	EDC17CP54	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
748	VAG (VW Group)	Bosch	EDC17CP74	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
50	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
51	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
52	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
539	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E84
48	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
53	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
49	VAG (VW Group)	Bosch	ME7.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21
186	VAG (VW Group)	Bosch	ME7.5.20 - ME7.5.30	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E42
293	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
723	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
168	VAG (VW Group)	Bosch	MED17.1 (rom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
218	VAG (VW Group)	Bosch	MED17.1 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
266	VAG (VW Group)	Bosch	MED17.1.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
792	VAG (VW Group)	Bosch	MED17.1.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
707	VAG (VW Group)	Bosch	MED17.1.1	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
378	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
690	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
800	VAG (VW Group)	Bosch	MED17.1.21	TC1793	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
128	VAG (VW Group)	Bosch	MED17.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
472	VAG (VW Group)	Bosch	MED17.5	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
147	VAG (VW Group)	Bosch	MED17.5.1	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
267	VAG (VW Group)	Bosch	MED17.5.1	TC1766	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
435	VAG (VW Group)	Bosch	MED17.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E21/E42
689	VAG (VW Group)	Bosch	MED17.5.2	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
334	VAG (VW Group)	Bosch	MED17.5.2 (rom)	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
179	VAG (VW Group)	Bosch	MED17.5.20	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
695	VAG (VW Group)	Bosch	MED17.5.21	TC1782	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
697	VAG (VW Group)	Bosch	MED17.5.24	TC1724	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
696	VAG (VW Group)	Bosch	MED17.5.5	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
715	VAG (VW Group)	Bosch	MED17.5.5	TC1762 / TC1766	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
358	VAG (VW Group)	Bosch	MED17.5.6	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)		E94
780	VAG (VW Group)	Bosch	MED17.5.6	TC1767	TF003	23 - INFINEON TRICORE BOSCH MEDC17 GPT VAG		E94
64	VAG (VW Group)	Bosch	MED9.1/MED9.5/MED9.5.10	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E58/E85
390	VAG (VW Group)	IAW Marelli	4AF	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
183	VAG (VW Group)	IAW Marelli	4AVP	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
835	VAG (VW Group)	IAW Marelli	4AV	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)		E101
184	VAG (VW Group)	IAW Marelli	4BV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
674	VAG (VW Group)	IAW Marelli	4CW	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
374	VAG (VW Group)	IAW Marelli	4GV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
185	VAG (VW Group)	IAW Marelli	4HV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
173	VAG (VW Group)	IAW Marelli	4TV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E101
735	VAG (VW Group)	IAW Marelli	9CV	SPC563M64	TF011	37 - MOTOROLA MPC56xxx SPC56x		E101
513	VAG (VW Group)	Siemens VDO	PCR2.1	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	OBDDII Unlock Patch	E131
75	VAG (VW Group)	Siemens VDO	SIMOS 5WP4 PPD1.x	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E69
174	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E69
214	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E69
512	VAG (VW Group)	Siemens VDO	SIMOS 8.x	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	OBDDII Unlock Patch	E134
89	Valtra Sisu (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
342	Volkswagen Truck	Bosch	EDC16C8	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND /	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) /	CPU GROUP /	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	PATCH UNLOCK /	CHECKSUM MOD./
58	Volkswagen Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
93	Volkswagen Truck (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		NO CHECKSUM
68	Volvo	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
113	Volvo	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
158	Volvo	Bosch	EDC17CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
681	Volvo	Bosch	EDC17CP48	TC1797	TF003	24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO		E94
743	Volvo	Bosch	EDC17CP68	TC1797	TF003	24 - INFINEON TRICORE BOSCH MEDC17 GPT VOLVO		E94
624	Volvo	Bosch	ME7 (AM29F400)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
325	Volvo	Bosch	ME7 (AM29F800)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
626	Volvo	Bosch	ME7 (AM29F800)	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)		E46
73	Volvo	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E70
421	Volvo	Denso	079700-9xxx	SH7058	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
326	Volvo	Denso	2.4	SH7058	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
499	Volvo	Denso	HP.2	SH7055	TF005	07 - RENESAS SH705x (TM007)		NO CHECKSUM
399	Volvo Penta	Bosch	EDC17CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94
357	Volvo Power Generator	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E80
138	Volvo Truck / Renault Truck	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E80
246	Volvo Truck / Renault Truck	TRW Motorola	EMS2 (EURO4/EURO5 version)	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55x (TM006)		E80
59	Volvo Truck / Volvo Penta	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E52
788	Volvo Truck	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
433	Weichai Truck (Weichai engines)	Bosch	EDC7 UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67
612	XCMG	Bosch	EDC7_U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55x/MPC56x (TM001)		E67/E133
559	Yale	Sagem	S3000	SH7055	TF005	07 - RENESAS SH705x (TM007)		E73
562	Yamaha	Denso	13S-8591A-00 MICRO 1	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
563	Yamaha	Denso	13S-8591A-00 MICRO 2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
555	Yamaha	Denso	14B-8591A-XX MICRO 1	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
556	Yamaha	Denso	14B-8591A-XX MICRO 2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
646	Yamaha	Denso	1RC-8591A-XX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
848	Yamaha	Denso	1WS-8591A-XX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
906	Yamaha	Denso	23P-8591A-XX MPC1	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
907	Yamaha	Denso	23P-8591A-XX MPC2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
834	Yamaha	Denso	2RC-8591A-XX	SH7058	TF005	07 - RENESAS SH705x (TM007)		E121
849	Yamaha	Denso	39P-8591A-XX	SH7055	TF005	07 - RENESAS SH705x (TM007)		E121
553	Yamaha	Denso	4C8-8591A-XX MICRO 1	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
554	Yamaha	Denso	4C8-8591A-XX MICRO 2	SH7054	TF005	07 - RENESAS SH705x (TM007)		E121
574	Yamaha	Melco	F8T9487x	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
866	Yamaha	Mitsubishi	55L-8591A-XX	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
842	Yamaha	Mitsubishi	5YU-8591A-XX	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
859	Yamaha	Mitsubishi	63P-8591A-XX	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
850	Yamaha	Mitsubishi	68V-8591A-XX	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
885	Yamaha	Mitsubishi	6CX-8591A-XXX	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
631	Yamaha	Mitsubishi	6D9-8591A-14	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
892	Yamaha	Mitsubishi	6EV-8591A-XX	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
899	Yamaha	Mitsubishi	8KJ-8591A-XX	MH8115F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
889	Yamaha	Mitsubishi	B57-8591A-XX	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
634	Yamaha	Mitsubishi	F8T81X	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
686	Yamaha	Mitsubishi	F8T820XXX	MH5XXXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
664	Yamaha	Mitsubishi	F8T84475	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
284	Yamaha	Mitsubishi	FX-SHO	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)		-
656	Yanmar	Bosch	EDC17CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)		E94